MULTI-POINT VEHICLE INSPECTION

Shop Sample Auto Repair **RO #** 1042 **Date** 2026-11-04

Tech John Smith **Customer** Jane Doe

Vehicle 2016 Honda Accord **VIN** 1HGCM00000A000000 **Miles** 81234

	G / Y / R	
Lights: head	G ☑ Y ☐ R ☐	
Lights: brake	G ☐ Y ☐ R ☐	
Lights: turn	G ☐ Y ☐ R ☐	
Lights: reverse	G ☐ Y ☐ R ☐	
Wipers / washer	G ☐ Y ☐ R ☐	
Horn	G ☐ Y ☐ R ☐	
Tire LF tread (32nds)	G ☐ Y ☐ R ☐	
Tire RF tread (32nds)	G ☐ Y ☐ R ☐	
Tire LR tread (32nds)	G ☐ Y ☐ R ☐	
Tire RR tread (32nds)	G ☐ Y ☐ R ☐	
Tire pressure	G ☐ Y ☐ R ☐	
Tire wear pattern	G ☐ Y ☐ R ☐	
Brakes: pad/shoe front	G ☐ Y ☑ R ☐	3mm front pads
Brakes: pad/shoe rear	G ☐ Y ☐ R ☐	
Rotors	G ☐ Y ☐ R ☐	
Brake fluid	G ☐ Y ☐ R ☐	
Fluid: oil	G ☐ Y ☐ R ☐	
Fluid: coolant	G ☐ Y ☐ R ☐	
Fluid: transmission	G ☐ Y ☐ R ☐	
Fluid: power steering	G ☐ Y ☐ R ☐	
Fluid: brake	G ☐ Y ☐ R ☐	
Fluid: washer	G ☐ Y ☐ R ☐	

Free template from greasegoose.xyz

Inspection continued

Belts	G ☐ Y ☐ R ☐	
Hoses	G ☐ Y ☐ R ☐	
Battery test result	G ☐ Y ☐ R ☐	
Battery terminals	G ☐ Y ☐ R ☐	
Filter: engine air	G ☐ Y ☐ R ☐	
Filter: cabin	G ☐ Y ☐ R ☐	
Shocks / struts	G ☐ Y ☐ R ☐	
Ball joints	G ☐ Y ☐ R ☐	
Tie rods	G ☐ Y ☐ R ☐	
Exhaust	G ☐ Y ☐ R ☐	
Leaks	G ☐ Y ☐ R ☐	
CV boots / axles	G ☐ Y ☐ R ☐	
Dash warning lights	G ☐ Y ☐ R ☐	

Tech recommendations

Replace front pads soon. Tires green.

Customer sign **Date**

Free template from greasegoose.xyz